



CURRENT OPENING

# Industrial Laborer

*Location: Salt Lake City, Utah*

Posting Date: 4/2020

Reports to: Wet Cast Foreman

FLSA Status: Hourly

Close Date: Until filled\*

## Looking for a job with stable hours, great benefits, and long-term security? Join our fantastic team!

We offer a work environment that values safety and team input, and provides opportunities to gain skills and grow your career.

### **ABOUT THE JOB**

Assist with manufacturing of concrete products.

### **ESSENTIAL FUNCTIONS & MAJOR RESPONSIBILITIES**

- Perform tasks involving strenuous manual labor in manufacturing a variety of concrete products.
- Support crew during concrete pours.
- Help maintain a clean jobsite by picking up and storing tools and equipment.
- Perform materials handling and storage.
- Wear a hard hat, safety glasses, steel-toe boots, and ear protection as needed.
- Read blueprints.
- Accurately place and properly secure box lid panels.
- Place the appropriate panels and C-clamps in the work area.
- Use a tape measure to set panels at indicated 90-degree angles, lengths, and widths and use C-clamps to secure the panels to each other.
- Accurately placed plywood inside the edges of the form.
- Use a tape measure, pencil, and power saw to cut the plywood according to specified dimensions.
- Place the cut pieces inside the forms at the outer edges, no securing is necessary, as the rebar will hold it in place.

- All dimensions are accurate and the block-out is secure.
- Determine whether Styrofoam block-outs are to be used, or if metal block-outs are more appropriate.
- As needed, place round weight blocks on the Styrofoam block-out; minimizing any movement.
- Evenly apply form oil to all form surfaces that will be exposed to wet concrete, without excess.
- Locate the bucket of form oil and the form oil brush, ensure there is sufficient oil in the bucket.
- All rebar place at proper spacing and fully secured with tie wire.
- As needed, use a tape measure to properly size the rebar pieces while using the rebar cutter machine.
- Spray green epoxy paint on any cut edges or nicked areas of the rebar, as needed.
- Using tie wire and a tie wire spinning tool, begin tying at 6", 8", 9" or 12" spacing, according to plans.
- Prepare round manhole lids.
- Cutting and placing rebar in round lids.
- Clean up work area.
- Setting grade lines.
- Place and support cast-in frames.

### **KNOWLEDGE, SKILLS & ABILITIES**

- Past experience working with hand tools, saws, air tools, grinders.

Full list of anticipated physical demands for this position and detail on our work environment is available on our application portal. Reasonable accommodations may be made to enable individuals with disabilities to perform the essential functions.

### **TO APPLY**

Sound like the job for you? [Click here](#) to apply online.

---

*Our organization maintains a drug-free workplace. Except where prohibited by state law, all offers of employment are conditioned upon successful passing of a drug test and background check.*

*Northwest Pipe Company is committed to equal employment opportunity and affirmative action. Minorities, females, veterans, and individuals with disabilities are encouraged to apply.*

*Northwest Pipe Company reserves the right to close the position, with or without notice, if a qualified candidate is identified prior to the close date.*